MATERIAL SAFETY DATA SHEET AMERICAN PEACOCK BLUE HH

Version Number 1.1 Revision Date 03/13/2014 Page 1 of 6 Print Date 3/20/2014

1. PRODUCT AND COMPANY IDENTIFICATION

POLYONE CORPORATION 33587 Walker Road, Avon Lake, OH 44012

Telephone Emergency telephone number	:	1 (440) 930-1000 or 1 (866) POLYONE CHEMTREC 1-800-424-9300 (24hrs for spill, leak, fire, exposure or accident).
Product name	:	AMERICAN PEACOCK BLUE HH
Product code	:	CC10128871
Chemical Name	:	Mixture
CAS-No.	:	Mixture
Product Use	:	Industrial Applications

2. COMPOSITION/INFORMATION ON INGREDIENTS

There are no known hazardous components above regulatory thresholds in this product.

3. HAZARDS IDENTIFICATION

EMERGENCY OVERVIEW

This mixture has not been evaluated as a whole. Information provided on the health effects of this product is based on individual components. All ingredients are bound and potential for hazardous exposure as shipped is minimal. However, some vapors may be released upon heating and the end-user (fabricator) must take the necessary precautions (mechanical ventilation, respiratory protection, etc.) to protect employees from exposure.

POTENTIAL HEALTH EFFECTS

Routes of Exposure:	: Inhalation, Ingestion, Skin contact
Acute exposure	
Inhalation	: Resin particles, like other inert materials, can be mechanically irritating.
Ingestion	: May be harmful if swallowed.
Eyes	: Resin particles, like other inert materials, are mechanically irritating to eyes.
Skin	: Experience shows no unusual dermatitis hazard from routine handling.
Chronic exposure	: Refer to Section 11 for Toxicological Information.

<u>PolyOne</u>

MATERIAL SAFETY DATA SHEET AMERICAN PEACOCK BLUE HH

Version Number 1.1 Revision Date 03/13/2014 Page 2 of 6 Print Date 3/20/2014

Medical Conditions Aggravated by Exposure:	: None known.
	4. FIRST AID MEASURES
Inhalation	: Move to fresh air in case of accidental inhalation of fumes from overheating or combustion. When symptoms persist or in all cases o doubt seek medical advice.
Ingestion	: Do not induce vomiting without medical advice. When symptoms persist or in all cases of doubt seek medical advice.
Eyes	: Rinse immediately with plenty of water, also under the eyelids, for at least 15 minutes. If eye irritation persists, seek medical attention.
Skin	: Wash off with soap and plenty of water. If skin irritation persists seek medical attention.
	5. FIREFIGHTING MEASURES
Flash point	: not applicable
Flammable Limits Upper explosion limit Lower explosion limit Auto-ignition temperature Suitable extinguishing media Special Fire Fighting Procedures Unusual Fire/Explosion Hazards	 not applicable not applicable not applicable Carbon dioxide blanket, Water spray, Dry powder, Foam. Fullface self-contained breathing apparatus (SCBA) used in positive pressure mode should be worn to prevent inhalation of airborne contaminants. Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), other hazardous materials, and smoke are all possible.
	6. ACCIDENTAL RELEASE MEASURES
Personal precautions	: Wear appropriate personal protection during cleanup, such as impervious gloves, boots and coveralls.
Environmental precautions	: Should not be released into the environment. The product should not be allowed to enter drains, water courses or the soil.
Methods for cleaning up	: Clean up promptly by sweeping or vacuum. Package all material in plastic, cardboard or metal containers for disposal.
	7. HANDLING AND STORAGE
Handling	: Take measures to prevent the build up of electrostatic charge. Heat only in areas with appropriate exhaust ventilation.

PolyOne.

MATERIAL SAFETY DATA SHEET AMERICAN PEACOCK BLUE HH

Version Number 1.1 Revision Date 03/13/2014 Page 3 of 6 Print Date 3/20/2014

		Keep containers dry and tightly closed to avoid moisture absorption and contamination. Keep in a dry, cool place.					
8. EXI	POSUR	RE CONTROLS/PE	ERSONAL PROTECTIO	ON			
Respiratory protection	:	No personal respira	atory protective equipment	t normally required.			
Eye/Face Protection	:	Safety glasses with side-shields					
Hand protection	:	Protective gloves					
Skin and body protection	:	Long sleeved clothing					
Additional Protective Measures	:	Safety shoes					
General Hygiene Considerations		Handle in accordance with good industrial hygiene and safety practice. Wash hands before breaks and at the end of workday.					
Engineering measures	:	Heat only in areas with appropriate exhaust ventilation. Provide appropriate exhaust ventilation at machinery.					
-	us comp	oonents above regula	atory thresholds in this pro	oduct.			
Exposure limit(s) There are no known hazardou 9.			atory thresholds in this pro	oduct.			
There are no known hazardou		ICAL AND CHEM id lets		oduct. : Not applicable : Not determined : Not established			
There are no known hazardou 9. Form Appearance Colour Odour	. PHYS : sol : pel : BL : ver	ICAL AND CHEM id lets JUE 'y faint	MICAL PROPERTIES Evapouration rate Specific Gravity Bulk density Vapour pressure	 Not applicable Not determined Not established not applicable 			
There are no known hazardou 9. Form Appearance Colour Odour Melting point/range	. PHYS : sol : pel : BL : ver : No	ICAL AND CHEM id llets JUE ry faint t determined	MICAL PROPERTIES Evapouration rate Specific Gravity Bulk density Vapour pressure Vapour density	 Not applicable Not determined Not established not applicable not applicable 			
There are no known hazardou 9. Form Appearance Colour Odour	. PHYS : sol : pel : BL : ver : No : not	ICAL AND CHEM id lets JUE 'y faint	MICAL PROPERTIES Evapouration rate Specific Gravity Bulk density Vapour pressure	 Not applicable Not determined Not established not applicable 			
There are no known hazardou 9. Form Appearance Colour Odour Melting point/range Boiling Point:	. PHYS : sol : pel : BL : ver : No : not : ins	ICAL AND CHEM id llets JUE cy faint t determined t applicable	MICAL PROPERTIES Evapouration rate Specific Gravity Bulk density Vapour pressure Vapour density pH	 Not applicable Not determined Not established not applicable not applicable 			
There are no known hazardou 9. Form Appearance Colour Odour Melting point/range Boiling Point:	. PHYS : sol : pel : BL : ver : No : not : ins 10.	ICAL AND CHEM id llets .UE cy faint it determined t applicable oluble .STABILITY AND	MICAL PROPERTIES Evapouration rate Specific Gravity Bulk density Vapour pressure Vapour density pH	 Not applicable Not determined Not established not applicable not applicable not applicable 			
There are no known hazardou 9. Form Appearance Colour Odour Melting point/range Boiling Point: Water solubility	. PHYS : sol : pel : BL : ver : No : not : ins 10.	ICAL AND CHEM id llets .UE cy faint it determined t applicable oluble .STABILITY AND	MICAL PROPERTIES Evapouration rate Specific Gravity Bulk density Vapour pressure Vapour density pH	 Not applicable Not determined Not established not applicable not applicable not applicable 			
There are no known hazardou 9. Form Appearance Colour Odour Melting point/range Boiling Point: Water solubility Stability	. PHYS : sol : pel : BL : ver : No : not : ins 10. : :	ICAL AND CHEM id lets .UE :y faint it determined t applicable oluble .STABILITY AND The product is stabl Will not occur.	MICAL PROPERTIES Evapouration rate Specific Gravity Bulk density Vapour pressure Vapour density pH D REACTIVITY le if stored and handled as kidizing agents and open fille	 Not applicable Not determined Not established not applicable not applicable not applicable 			
There are no known hazardou 9. Form Appearance Colour Odour Melting point/range Boiling Point: Water solubility Stability Hazardous Polymerization	. PHYS : sol : pel : BL : ver : No : not : ins 10. : : :	id llets .UE cy faint t determined t applicable oluble .STABILITY ANE The product is stabl Will not occur. Keep away from ox decomposition, do n	MICAL PROPERTIES Evapouration rate Specific Gravity Bulk density Vapour pressure Vapour density pH D REACTIVITY le if stored and handled as kidizing agents and open fille	 Not applicable Not determined Not established not applicable not applicable not applicable 			

PolyOne.

MATERIAL SAFETY DATA SHEET AMERICAN PEACOCK BLUE HH

Version Number 1.1 Revision Date 03/13/2014 Page 4 of 6 Print Date 3/20/2014

	12. ECOLOGICAL INFORMATION
Persistence and degradability	: Not readily biodegradable.
Environmental Toxicity	: Chemicals are not readily available as they are bound within the polymer matrix.
Bioaccumulation Potential	: Chemicals are not readily available as they are bound within the polymer matrix.
Additional advice	: no data available
	13. DISPOSAL CONSIDERATIONS
Product	: Like most thermoplastic plastics the product can be recycled. When possible recycling is preferred to disposal or incineration. The generator of waste material has the responsibility for proper waste classification, transportation and disposal in accordance with applicable federal, state/provincial and local regulations.
Contaminated packaging	: Recycling is preferred when possible. The generator of waste material has the responsibility for proper waste classification, transportation and disposal in accordance with applicable federal, state/provincial and local regulations.
	14. TRANSPORT INFORMATION
U.S. DOT Classification	: Not regulated for transportation.
ICAO/IATA	: Refer to specific regulation.
IMO/IMDG (maritime)	: Refer to specific regulation.
	15. REGULATORY INFORMATION
US Regulations:	
OSHA Status	: There are no known hazardous components above regulatory thresholds in this product.
TSCA Status	: All components of this product are listed on or exempt from the TSCA Inventory.

PolyOne.

MATERIAL SAFETY DATA SHEET AMERICAN PEACOCK BLUE HH

Version Number 1.1 Revision Date 03/13/2014 Page 5 of 6 Print Date 3/20/2014

NPRI ID#

not applicable

California Proposition : Not applicable 65

SARA Title III Section 302 Extremely Hazardous Substance

Unless specific chemicals are identified under this section, this product is Not Applicable under this regulation

SARA Title III Section 313 Toxic Chemicals:

Unless specific chemicals are identified under this section, this product is Not Applicable under this regulation

Canadian Regulations:

 National Pollutant Release Inventory (NPRI)

 Chemical Name
 CAS-No.
 Weight percent

Phthalocyanine green			1328-53-6	0.10 - 1.00	
WHMIS Classification	:	Inventories or an product is on the	oonents of this produ re exempt. However e Canadian Non-Do Canada is restricted	, at least one com mestic Substance	ponent of this
National Inventories:					
Australia AICS	:	Not determined			
China IECS	:	Not determined			
Europe EINECS	:	Not determined			
Japan ENCS	:	Not determined			
Korea KECI	:	Not determined			
Philippines PICCS	:	Not determined			
		16. OTHER IN	NFORMATION		

PolyOne.

MATERIAL SAFETY DATA SHEET AMERICAN PEACOCK BLUE HH

Version Number 1.1 Revision Date 03/13/2014 Page 6 of 6 Print Date 3/20/2014

The information provided in this Safety Data Sheet is correct to the best of our knowledge, information and belief at the date of its publication. The information given is designed only as a guidance for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered a warranty or quality specification. The information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process, unless specified in the text.